

Change Record

Part Number DS19500-011Page 1 of 1

Description	LUG UPGRADE INSTALLATION, 206A/B FLAT STOP
-------------	--

[illegible]

Change Record

Part Number DSI 9502-011
Description GAS SPRING KIT

Page 1 of 1[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9505-011

Description: BASKET CONVERSION, LH[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9505-012

Description: BASKET CONVERSION, RH[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9505-013

Description: BASKET CONVERSION, HOOPS ONLY

[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9506-011

Description: INSTALLATION MODIFICATION

[illegible]

Change Record

Part Number DSI 9507-011
Description CARGO POD COMPATIBILITY

Page 1 of 1

[illegible]

Change Record

Part Number DSI 9508-011
Description Rivet Kit

Page 1 of 1[illegible]

Change Record

Part Number DSI 9515-011
Description LUG MODIFICATION

Page ____ of ____

[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9517-011

Description: WEARPLATE

[illegible]

Change Record

Part Number DSI 9519-011
Description REPLACEMENT BUSHING INSTALLATION

Page 1 of 1[illegible]

Change Record

Part Number DSI 9522-011
Description PLACARDS, PORTUGUESE (AS 350)

Page 1 of 1[illegible]

Change Record

Part Number DSI 9522-021
Description PLACARDS, PORTUGUESE (EC 130)

Page 1 of 1[illegible]

Change Record

Part Number DSI 9524-011
Description LUG INSTALLATION

Page 1 of 1[illegible]

Change Record

Part Number DSI 9525-011
Description STEP CUSHION INSTALLATION (591-111A)

Page 1 of 1[illegible]

Change Record

Part Number DSI 9525-013
Description STEP CUSHION INSTALLATION (591-113/119)

Page 1 of 1[illegible]

Change Record

Part Number DSI 9525-015
Description STEP CUSHION INSTALLATION (591-115)

Page 1 of 1

[illegible]

Change Record

Part Number DSI 9525-017
Description STEP CUSHION INSTALLATION (591-117A)

Page 1 of 1[illegible]

Change Record

Part Number DSI 9528-011
Description SPACEPOD FLOOR MODIFICATION, LH

Page 1 of 1[illegible]

Change Record

Part Number DSI 9528-012
Description SPACEPOD FLOOR MODIFICATION, RH

Page 1 of 1[illegible]

Change Record

Part Number DSI 9529-011 / -012

Page 1 of 1Description SPACEPOD CONVERSION, LH / RH[illegible]

Change Record

Part Number DS19534-011
Description DECAL (PORTUGUESE)

Page 1 of 1[illegible]

Change Record

Part Number DSI 9534-013
Description 300 HOUR INSPECTION, PORTUGUESE

Page 1 of 1[illegible]

Change Record

Part Number DSI 9535-011
Description LABEL PLATE, 441 BASKET

Page (of)

[illegible]

Change Record

Part Number DS19535-013
Description LABEL PLATE, 445 BASKET

Page 1 of 1[illegible]

Change Record

Part Number DS1 9535-015Page 1 of 7

Part Number	541-1585-015
Description	LABEL PLATE, 541 BASKET

[illegible]

Change Record

Part Number DSI 9535-017
Description LABEL PLATE, 545 BASKET

Page 1 of 1[illegible]

Change Record

Part Number DS19542-041

Page 1 of 1

Description BASKET MODIFICATION

[illegible]

Change Record

Part Number DSI 9562-011

Page 1 of 1

Description COMPATIBILITY INSTALLATION

[illegible]

Change Record

Part Number DS19566-011

Page ____ of ____

Description _____

[illegible]

Change Record

Part Number DS19567-011

Page 1 of 1

Description DOOR PROP INSTALLATION

[illegible]

Change Record

Part Number DSI 9569-011

Page 1 of 1

Description HANDLE INSTALLATION

[illegible]

Change Record

Part Number DSI 9571-011

Page 1 of 1

Description BOLT SUBSTITUTION

[illegible]

Change Record

Part Number DSI 9577-011

Page 1 of 1

Description CUSHION INSTALLATION

[illegible]

Change Record

Part Number DS1 9578-011

Page 1 of 1

Description MIRROR ARM UPGRADE

[illegible]

Change Record

Part Number DS19578-013Page 1 of 1

Description MIRROR ARM UPGRADE

[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9579-011

Description: COMPOSITE DOOR UPGRADE

[illegible]

Change Record

Part Number DSI 9585-011

Page 1 of 1Description TORSION SPRING REPLACEMENT[illegible]

Change Record

Part Number DS19585-013

Page 1 of 1

Description LOCK BARREL SPRING REPLACEMENT

[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9586-011

Description: DOOR PROP UPGRADE[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9586-013

Description: DOOR PROP UPGRADE[illegible]

Change Record

PAGE 1 OF 1

Part Number: DSI 9594-011

Description: FWD GROUND HANDLING SPACER MODIFICATION

[illegible]

Change Record

Part Number DSI 9597-011

Page 1 of 1

Description PLACARD INSTALLATION

[illegible]

Change Record

Part Number DS1 9599-011

Page 1 of 1

Description SQUIRREL CHEEK COMPATIBILITY

[illegible]